

$S_p = 5,2 \text{ mA/V}$
 $R_i = 400 \text{ k}$
 $P_a = \text{max. } 2,8 \text{ W}$

$S_T = 8,5 \text{ mA/V}$
 $R_i = 5 \text{ k}$
 $\mu = 40$
 $P_a = \text{max. } 2,5 \text{ W}$

