

A
 $S = 1,6 \text{ mA/V}$
 $\mu = 64$
 $R_i = 40 \text{ k}$
 $P_a = \text{max. } 1,5 \text{ W}$

B
 $S = 7,5 \text{ mA/V}$
 $\mu = 6$
 $R_i = 800 \Omega$
 $P_a = \text{max. } 10 \text{ W}$

