

$S = 11 \text{ mA/V}$   
 $V_{g1} = -11 \text{ V}$   
 $R_i = 7 \text{ k}$   
 $P_a = \text{max. } 16 \text{ W}$

