

$S_p = 9 \text{ mA/V}$
 $R_i = 400 \text{ k}$
 $P_a = \text{max. } 3,25 \text{ W}$

$S_T = 4 \text{ mA/V}$
 $R_i = 17,5 \text{ k}$
 $\mu = 70$
 $P_a = \text{max. } 1 \text{ W}$

